

CPUC SUBSTATION AUDIT FINDINGS
PG&E McMaude Headquarters
February 5 – 9, 2024

I. Records Review

During the substation audit, Electric Safety and Reliability Branch (ESRB) reviewed the following standards, procedures, and records for PG&E's McMaude Headquarters (HQ):

- List of all assigned PG&E substations
- Map showing all assigned PG&E substations in the McMaude HQ
- PG&E Substation Maintenance and Construction (SM&C) Manual, Utility Standard: TD-3322M, Revisions 9 and 11, with attachments 3 through 6, 8, and 11
- PG&E Utility Standard: TD-3328P attachments 2 through 4, Revision 0
- PG&E Mobile Inspection Form, Utility Standard: TD-3468-01-F01, Revision 1
- PG&E Substation Equipment Maintenance Requirements, Utility Standard: TD-3322S, Revisions 8 and 9, with attachments 2 through 12
- PG&E Substation Supplemental Inspection Program, Utility Standard: TD-3328S, Revision 2, with attachment 1
- PG&E Substation Asset Performance Management (APM) Process, Utility Procedure: TD-3320P-36, Revision 0
- PG&E Substation SAP Work Management System (WMS) Process, Utility Procedure: TD-3320P-12, Revision 7
- PG&E SM&C Manual – Infrared Inspections, Utility Standard: TD-3322M, Revision 11
- PG&E SM&C Manual – Insulating Oil, Utility Standard: TD-3322M, Revisions 7 and 8
- PG&E Accumulated Critical Current (ACC) Process, Utility Standard: TD-3320P-12, Revision 0
- PG&E SM&C Manual – Substation Batteries, Utility Standard: TD-3322M, Revision 13
- PG&E Substation Fire Protection Systems and Equipment – Inspection, Test and Maintenance: TD-3320P-07, Revision 3
- PG&E Substation General Work Procedures, Utility Standard: TD-3320S, Revision 2
- Explanation of PG&E inspector training policies
- List of all substation inspections conducted in the last five years for McMaude HQ
- List of all open/pending, completed, cancelled, and late work orders and maintenance items in the previous five years
- Equipment lists for ESRB selected substations
- Single-line diagrams of ESRB selected substations
- Last two visual inspection checklists for ESRB selected substations
- List of transformer banks that operated beyond nameplate capacity for the last five years for ESRB selected substations.
- Infrared Testing records for ESRB selected substations in the last two years
- Most recent oil sample test results for ESRB selected substations
- Most recent electric test results for ESRB selected substations
- Training records for all substation and maintenance personnel in the past five years
- Other relevant substation inspections for the past five years for ESRB selected substations
- Internal audit findings for McMaude HQ for the past five years

II. Records Violations

ESRB observed the following violations during the records review portion of the audit:

General Order (GO) 174, Rule 12, General states in part:

“Design, construction and maintenance should be performed in accordance with accepted good practices for the given local conditions known at the time by those responsible.”

1. PG&E’s Substation Maintenance and Construction Manual (SM&C), “Infrared Inspections”, Utility Standard: TD-3322M-09¹ details PG&E’s maintenance procedures for Infrared Inspections as follows:

“The repair priority codes shown in Table 1 determine the actions required for re-inspection or equipment repair.”

Table 1: Repair Priorities

| Temperature Rise (ΔT) | | | | | | |
|---------------------------------|--------------------|--|----------|------------|-----------------------|---------------------------|
| SAP Repair Priority Codes | Action | Direct View Targets Percent of Rated Load | | | Indirect View Targets | Main Tank compared to LTC |
| | | 0-40% | 41-81% | 81-100% | | |
| A | Immediate repair | > 100°C | | > 125°C | > 10°C | > -5°C |
| A | Repair 30 days | 80°-100°C | | 100°-125°C | NA | |
| B | Repair 90 days | 86°-79°C | NA | 80°-99°C | 5°-9°C | -4° to -5°C |
| B | Re-inspect 90 days | 15°-59°C | 15°-79°C | | 2°-4°C | -2° to -3°C |
| NA | No action | < 15°C | | | < 2°C | ≤ -1°C |

- a. Based on the SM&C Infrared Inspections Table 1, ESRB found that PG&E did not complete the 90 day re-inspect after an infrared inspection within the required time frame at the Basalt Substation. On October 14, 2022, PG&E found that Motor Operate Air Switch (MOAS) 69 had a hot spot and needed to be reinspected in 90 days (EC Tag #124732338). However, the reinspection of MOAS 69 did not occur until January 25, 2023, 103 days after the previous inspection.

[PG&E Response:](#)

We agree that we did not perform the Basalt substation IR re-inspection of the Motor-operated air switch 69 within the 90-day timeframe per TD-3322M-09.

¹ PG&E Utility Standard TD3322M-09, April 6, 2023, Revision

- b. Based on the Infrared Inspection procedure, PG&E requires any anomalies to be assigned a repair priority code of either Priority A, for immediate repair or repair in 30 days, or Priority B, for repair or reinspect in 90 days. However, ESRB identified 3 hot-spot related notifications in the McMaude HQ that were assigned Priority E, as shown in Table 2.

Table 2: Infrared Inspection Priority E Hot-Spot Notifications

| Substation | Notification Number | Priority | Notification Date | Completion Date | Out-of-Compliance Date |
|------------|---------------------|----------|-------------------|-----------------|------------------------|
| Bahia | 118596883 | E | 1/9/2020 | 4/20/2020 | 1/1/2022 |
| Dunbar | 121448392 | E | 6/2/2021 | 7/14/2021 | 1/1/2023 |
| Napa | 121892991 | E | 8/11/2021 | 8/31/2021 | 1/1/2023 |

ESRB noted that PG&E TD-3322S permits staff to deviate from procedures if the line supervisor obtains approval from the local transmission field specialist. It also requires that the variance must be documented in the long-text field of the SAP order for the maintenance work and refer to the approved form TD-3322M-F90 “SM&C Manual Procedure Variance Review”. However, the notifications above do not have any variances noted in the long-text field and do not refer to a form TD-3322M-F90.

PG&E Response:

We agree that all three (3) notifications listed below were created with the incorrect priority code and we have corrected all three notifications within our system of record, SAP. However, all three notifications were completed within the allowed timeframe for a B-priority LC notification per TD-3322S so should not be considered a violation of G.O. 174, Rule 12. Please see below for the updated dates provided in Table1PGE.

Table1PGE

| Substation | Notification No | Priority | Completion Date | OOB Date | Status |
|------------|-----------------|----------|-----------------|------------|--------|
| Bahia | 118596883 | B | 04/20/2020 | 6/1/2020 | Closed |
| Dunbar | 121448392 | B | 07/14/2021 | 10/1/2021 | Closed |
| Napa | 121892991 | B | 8/31/2021 | 01/01/2022 | Closed |

We are aware of this persistent issue with pre-2023 IR data and CAP 120564870 was created to perform an apparent cause evaluation (ACE). From this, we established the preventative measure of having all reinspection or repair LC notifications automatically created through the Asset Performance Management (APM) software when an IR anomaly is identified. This enhancement was released in early 2022 and now ensures that all LC notifications for reinspection/repairs are created timely and with the correct priority codes.

2. PG&E Substation Equipment Maintenance Requirements, Utility Standard: TD-3322S², establishes PG&E’s required end dates and out-of-compliance dates as follows:

Table 3: Due Dates Per Priority Code

| Priority Code | Required End Date | Out-of-Compliance Date |
|---------------|-----------------------|---|
| A | Within 30 days | Close notifications (after removing the hazard [make safe] with either permanent or temporary repairs within 30 days. Create a new lower priority notification immediately for any remaining work that will exceed 30 days. |
| B | Within 90 days | The out-of-compliance date is the 1 st day of the 2 nd month following the month in which the repair date occurs. |
| E | Within 365 days | The out-of-compliance date is the 1 st day of the year following the year in which the required end date occurs. |
| F | Greater than 365 days | There is no out-of-compliance date. This work will be completed when it is operationally efficient to perform the work. |

Based on Table 3 above, ESRB noted 96 notifications that were closed after their out-of-compliance dates and 2 notifications that are still open past their out-of-compliance date, as of January 16, 2024. Therefore, PG&E did not perform maintenance in accordance with accepted good practices described in Utility Standard TD-3322S. See Table 4 below for the past-due Line Corrective (LC) notifications.

Table 4: Overdue LC Notifications

| Notification Number | Priority | Notification Date | Completion Date | Out-of-Compliance Date | Days Late |
|---------------------|----------|-------------------|-----------------|------------------------|-----------|
| 127413184 | A | 11/4/2023 | 12/20/2023 | 12/4/2023 | 16 |
| 125390850 | B | 1/24/2023 | 12/3/2023 | 6/1/2023 | 185 |
| 123788576 | B | 6/7/2022 | 1/26/2023 | 11/1/2022 | 86 |
| 123794505 | B | 6/7/2022 | 1/26/2023 | 11/1/2022 | 86 |
| 123801367 | B | 6/8/2022 | 1/26/2023 | 11/1/2022 | 86 |
| 121636373 | B | 6/29/2021 | 1/11/2022 | 11/1/2021 | 71 |
| 117931715 | B | 9/26/2019 | 3/27/2020 | 2/1/2020 | 55 |
| 124345612 | B | 8/10/2022 | 2/22/2023 | 1/1/2023 | 52 |
| 124268358 | B | 7/15/2022 | 1/18/2023 | 12/1/2022 | 48 |
| 123767649 | B | 5/27/2022 | 11/8/2022 | 10/1/2022 | 38 |
| 123749147 | B | 5/27/2022 | 10/28/2022 | 10/1/2022 | 27 |
| 123754095 | B | 5/27/2022 | 10/28/2022 | 10/1/2022 | 27 |
| 123758263 | B | 5/27/2022 | 10/28/2022 | 10/1/2022 | 27 |
| 123758539 | B | 5/27/2022 | 10/28/2022 | 10/1/2022 | 27 |
| 123767538 | B | 5/27/2022 | 10/27/2022 | 10/1/2022 | 26 |

| | | | | | |
|-----------|---|------------|------------|-----------|-----|
| 123758530 | B | 5/27/2022 | 10/26/2022 | 10/1/2022 | 25 |
| 120204794 | B | 12/9/2020 | 5/24/2021 | 5/1/2021 | 23 |
| 119754833 | B | 7/3/2020 | 11/13/2020 | 11/1/2020 | 12 |
| 119730613 | B | 6/30/2020 | 11/7/2020 | 11/1/2020 | 6 |
| 124268354 | B | 7/15/2022 | 12/7/2022 | 12/1/2022 | 6 |
| 126583104 | B | 6/16/2023 | 11/7/2023 | 11/1/2023 | 6 |
| 126583103 | B | 6/16/2023 | 11/6/2023 | 11/1/2023 | 5 |
| 122511896 | B | 12/7/2021 | 5/4/2022 | 5/1/2022 | 3 |
| 122511957 | B | 12/7/2021 | 5/4/2022 | 5/1/2022 | 3 |
| 121548632 | B | 6/14/2021 | 11/2/2021 | 11/1/2021 | 1 |
| 114497017 | E | N/A | 3/1/2019 | 1/1/2019 | 59 |
| 125265805 | E | N/A | 5/7/2023 | 5/1/2023 | 6 |
| 124882269 | E | N/A | 3/2/2023 | 3/1/2023 | 1 |
| 124882270 | E | N/A | 3/2/2023 | 3/1/2023 | 1 |
| 125311328 | E | N/A | 5/2/2023 | 5/1/2023 | 1 |
| 117672303 | E | 6/3/2019 | 3/28/2022 | 1/1/2021 | 451 |
| 119769633 | E | 7/2/2020 | 1/26/2023 | 1/1/2022 | 390 |
| 116966422 | E | 4/1/2019 | 12/20/2021 | 1/1/2021 | 353 |
| 121601289 | E | 6/25/2021 | 12/13/2023 | 1/1/2023 | 346 |
| 121601957 | E | 6/25/2021 | 12/13/2023 | 1/1/2023 | 346 |
| 121602260 | E | 6/25/2021 | 12/13/2023 | 1/1/2023 | 346 |
| 121586200 | E | 6/22/2021 | 12/7/2023 | 1/1/2023 | 340 |
| 121586422 | E | 6/22/2021 | 12/7/2023 | 1/1/2023 | 340 |
| 121586427 | E | 6/22/2021 | 12/7/2023 | 1/1/2023 | 340 |
| 121586429 | E | 6/22/2021 | 12/7/2023 | 1/1/2023 | 340 |
| 121589188 | E | 6/23/2021 | 12/7/2023 | 1/1/2023 | 340 |
| 121657968 | E | 6/27/2021 | 12/7/2023 | 1/1/2023 | 340 |
| 121661220 | E | 6/27/2021 | 12/7/2023 | 1/1/2023 | 340 |
| 121657695 | E | 6/27/2021 | 12/7/2023 | 1/1/2023 | 340 |
| 117330548 | E | 5/5/2019 | 12/2/2021 | 1/1/2021 | 335 |
| 122548910 | E | 12/15/2021 | 10/27/2023 | 1/1/2023 | 299 |
| 121617321 | E | 6/26/2021 | 9/22/2023 | 1/1/2023 | 264 |
| 121618763 | E | 6/26/2021 | 9/22/2023 | 1/1/2023 | 264 |
| 119754514 | E | 9/10/2020 | 8/16/2022 | 1/1/2022 | 227 |
| 119754516 | E | 9/10/2020 | 8/16/2022 | 1/1/2022 | 227 |
| 119754517 | E | 9/10/2020 | 8/16/2022 | 1/1/2022 | 227 |
| 119779150 | E | 9/10/2020 | 8/16/2022 | 1/1/2022 | 227 |
| 119779158 | E | 9/10/2020 | 8/16/2022 | 1/1/2022 | 227 |
| 119779211 | E | 9/10/2020 | 8/16/2022 | 1/1/2022 | 227 |
| 119997671 | E | 9/10/2020 | 8/16/2022 | 1/1/2022 | 227 |
| 119997673 | E | 9/10/2020 | 8/16/2022 | 1/1/2022 | 227 |

| | | | | | |
|-----------|---|------------|-----------|----------|------|
| 121538824 | E | 6/13/2021 | 8/16/2023 | 1/1/2023 | 227 |
| 121535891 | E | 6/13/2021 | 8/11/2023 | 1/1/2023 | 222 |
| 121536517 | E | 6/13/2021 | 8/11/2023 | 1/1/2023 | 222 |
| 121537266 | E | 6/13/2021 | 8/11/2023 | 1/1/2023 | 222 |
| 121539394 | E | 6/13/2021 | 8/11/2023 | 1/1/2023 | 222 |
| 121587452 | E | 6/23/2021 | 8/11/2023 | 1/1/2023 | 222 |
| 121587454 | E | 6/23/2021 | 8/11/2023 | 1/1/2023 | 222 |
| 121587459 | E | 6/23/2021 | 8/11/2023 | 1/1/2023 | 222 |
| 121588220 | E | 6/23/2021 | 8/11/2023 | 1/1/2023 | 222 |
| 117173562 | E | 4/29/2019 | 6/14/2021 | 1/1/2021 | 164 |
| 119769527 | E | 7/2/2020 | 6/2/2021 | 1/1/2021 | 152 |
| 119719151 | E | 9/4/2020 | 5/24/2022 | 1/1/2022 | 143 |
| 119719152 | E | 9/4/2020 | 5/24/2022 | 1/1/2022 | 143 |
| 119719153 | E | 9/4/2020 | 5/24/2022 | 1/1/2022 | 143 |
| 119754518 | E | 9/10/2020 | 5/24/2022 | 1/1/2022 | 143 |
| 119754519 | E | 9/10/2020 | 5/24/2022 | 1/1/2022 | 143 |
| 119754580 | E | 9/10/2020 | 5/24/2022 | 1/1/2022 | 143 |
| 119997676 | E | 9/10/2020 | 5/24/2022 | 1/1/2022 | 143 |
| 121561081 | E | 6/17/2021 | 5/20/2023 | 1/1/2023 | 139 |
| 122112100 | E | 9/27/2021 | 5/20/2022 | 1/1/2022 | 139 |
| 121560760 | E | 6/17/2021 | 4/30/2023 | 1/1/2023 | 119 |
| 121560766 | E | 6/17/2021 | 4/30/2023 | 1/1/2023 | 119 |
| 121626322 | E | 6/23/2021 | 4/30/2023 | 1/1/2023 | 119 |
| 121630097 | E | 6/23/2021 | 4/30/2023 | 1/1/2023 | 119 |
| 118263413 | E | 8/30/2019 | 4/24/2021 | 1/1/2021 | 113 |
| 121560769 | E | 6/17/2021 | 4/22/2023 | 1/1/2023 | 111 |
| 121629187 | E | 6/23/2021 | 4/22/2023 | 1/1/2023 | 111 |
| 121629570 | E | 6/23/2021 | 4/22/2023 | 1/1/2023 | 111 |
| 117170266 | E | 3/30/2019 | 4/15/2021 | 1/1/2021 | 104 |
| 117554548 | E | 5/9/2019 | 4/15/2021 | 1/1/2021 | 104 |
| 118264732 | E | 11/22/2019 | 4/15/2021 | 1/1/2021 | 104 |
| 119997421 | E | 11/8/2020 | 4/12/2021 | 1/1/2021 | 101 |
| 121577833 | E | 6/13/2021 | 4/7/2023 | 1/1/2023 | 96 |
| 120218688 | E | 12/17/2020 | 3/28/2022 | 1/1/2022 | 86 |
| 117268532 | E | 4/23/2019 | 3/15/2021 | 1/1/2021 | 73 |
| 114963052 | E | 9/11/2018 | 3/9/2020 | 1/1/2020 | 68 |
| 120137281 | E | 11/20/2020 | 2/28/2022 | 1/1/2022 | 58 |
| 119528807 | E | 6/23/2020 | 2/9/2021 | 1/1/2021 | 39 |
| 115069814 | E | 10/3/2018 | 2/8/2020 | 1/1/2020 | 38 |
| 121482681 | E | 6/5/2021 | N/A | 1/1/2023 | *380 |
| 122548792 | E | 12/15/2021 | N/A | 1/1/2023 | *380 |

*Calculated from January 16, 2024, the date when the notification data was received from PG&E.

PG&E Response:

We agree with 92 of the above 97 record violations cited in table “Table 4: Overdue LC Notifications”. Please see the breakdown of these notifications in Table 2PGE below.

| PG&E Code | CPUC “Overdue LC Notifications” | PG&E Agrees overdue | PG&E Disagree completed on-time |
|--------------|---------------------------------|---------------------|---------------------------------|
| A | 1 | 1 | 0 |
| B | 24 | 23 | 1 |
| E | 72 | 70 | 4 |
| F | - | - | - |
| Total | 97 | 92 | 5 |

We disagree with five of the record violations cited in “Table 4: Overdue LC Notifications.”

- Notifications 124268354, 114963052, 117330548, 119997421 and 117672303 were all cancelled; however, these were not properly labeled in the system (SAP) at the time we provided the pre-audit data request (PADR). Therefore, these five notifications are not considered past-due.

III. Field Inspection

During the field inspection, ESRB inspected the following 19 substations:

| Substation | City |
|---------------------------|-------------|
| Oakmont North Substation | Santa Rosa |
| Oakmont South Substation | Santa Rosa |
| Monroe Substation | Santa Rosa |
| Ignacio Substation | Ignacio |
| Stafford Substation | Novato |
| Petaluma A Substation | Petaluma |
| Corona Substation | Petaluma |
| Cotati Substation | Cotati |
| Mirabel Substation | Forestville |
| Fitch Mountain Substation | Healdsburg |
| Windsor Substation | Windsor |
| Silverado Substation | St. Helena |
| Napa Substation | Napa |

| | |
|--------------------------|---------------|
| Basalt Substation | Napa |
| Parkway Substation | Vallejo |
| Skaggs Island Substation | Skaggs Island |
| San Rafael Substation | San Rafael |
| Greenbrae Substation | Larkspur |
| Bolinas Substation | Bolinas |

IV. Field Inspection – Violations List

ESRB observed the following violations of GO 174, Rule 12 during the field inspection:

GO 174, Rule 12, General states in part:

“...Substations shall be designed, constructed and maintained for their intended use, regard being given to the conditions under which they are to be operated, to promote the safety of workers and the public and enable adequacy of service.

Design, construction, and maintenance should be performed in accordance with accepted good practices for the given local conditions known at the time by those responsible.”


PG&E Response:

We appreciate the insight and feedback from the ESRB, as well as the support in helping us achieve our stand that everyone and everything is always safe. We agree with 20 of the ESRB’s findings of violation and are committed to remedying these issues and striving to reduce and eliminate such findings in the future.

We do not believe some of the field observations qualify as violations of GO 174, Rule 12. Our Substation Inspection Program focuses on monthly and bi-monthly station inspections, along with our Enhanced Inspections (EI), Quality Verification (QV) audits, and Annual Infrared (IR) Inspections. These different levels of visual and technical assessments are conducted to indicate abnormal conditions before the equipment fails and to prevent unsafe events. 74 of the ESRB’s observations made during the field portion of the audit were previously identified and properly recorded in our system of record (SAP) as abnormal conditions during planned inspections. Each of these notifications were identified timely by our QEWS and scheduled for the appropriate corrective action in accordance with our maintenance standard/procedures and GO 174 requirements. Therefore, we do not believe that these 74 notifications qualify as GO 174, Rule 12 violations.

1. Oakmont North Substation

1.1. The station has expired eye wash. PG&E has existing Notification #128026970 for this issue.



PG&E Response:

We agree with the finding of expired eye wash at Oakmont North Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128026970. We will complete this work based on current work prioritization and material availability.

2. Oakmont South Substation

- 2.1. The station has expired eye wash. PG&E has existing Notification #128026980 for this issue.



PG&E Response:

We agree with the finding of expired eye wash at Oakmont South Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128026980. We will complete this work based on current work prioritization and material availability.

3. Monroe Substation

- 3.1. Station batteries have corrosion. PG&E has existing Notification #128027130 for this issue.



PG&E Response:

We agree with the finding of corroded batteries at Monroe Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027130. We will complete this work based on current work prioritization and material availability.

- 3.2. Transformer Bank 1 oil filtration system has oil leaks and a leaking motor pump.
PG&E has existing Notification #128027469 for this issue.



PG&E Response:

We agree with the finding of the LTC oil filtration leak at Monroe Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027469. We will complete this work based on current work prioritization and material availability.

3.3. Transformer Bank 3 has a faded and illegible gauge.



PG&E Response:

We agree with the finding of an illegible gauge at Transformer Bank 3. We created notification 128139480, added it to the workplan, and will be completed based on current work prioritization and material availability.

3.4. Transformer Bank 5 low side bushings have oil contamination. PG&E has existing Notification #128027254 for this issue.



PG&E Response:

We agree with the finding that Transformer Bank 5 low side bushings have contamination at Monroe Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027254. We will complete this work based on current work prioritization and material availability.

3.5. Transformer Bank 5 high side bushings have foggy and illegible gauges.



PG&E Response:

We agree with the finding that Transformer bank 5 high side bushings have faded gauges at Monroe Substation. We created notification 128139481, added it to the workplan, and will be completed based on current work prioritization and material availability.


3.6. Circuit Switcher 136 has a thermostat that needs to be readjusted to prevent overheating.



PG&E Response:

We agree with the finding of circuit switcher 136 had a thermostat needing to be adjusted at Monroe Substation. We created notification 128139456 and this work was completed on 02/27/24.

3.7. Circuit Switcher 126 has a bird's nest.



PG&E Response:

We agree with the finding of a bird's nest forming at Circuit Switcher 126 at Monroe Substation. We created notification 128139457 and this work was completed on 02/27/24.

3.8. Circuit Breaker 2103 has a faded counter. PG&E has existing Notification #128027460 for this issue.



PG&E Response:

We agree with the finding of a faded counter on Circuit Breaker 2103 at Monroe Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027460. We will complete this work based on current work prioritization and material availability.

4. Ignacio Substation

4.1. Station has expired eye wash in 60kV battery room. PG&E has existing Notification #128029626 for this issue.



PG&E Response:

We agree with the finding of expired eye wash at Ignacio Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029626. This work was completed on 02/28/2024.

- 4.2. Station 60kV batteries have corrosion. PG&E has existing Notification #128029628 for this issue.



PG&E Response:

We agree with the finding of corroded batteries at Ignacio Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029628. We will complete this work based on current work prioritization and material availability.

4.3. Transformer Bank 6 oil filtration system motor needs to be replaced.



PG&E Response:

We agree with the finding that the motor for bank 6 oil filtration system was turned off, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. The electrician turned this unit back on during the field audit and no issues have occurred since.


4.4. Transformer Bank 6 has a dirty pad from bird droppings. PG&E has existing Notification #128029580 for this issue.



PG&E Response:

We agree with the finding that Transformer Bank 6 had bird droppings at Ignacio Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029580. We will complete this work based on current work prioritization and material availability.

- 4.5. Transformer Bank 4 Spare Phase has an empty nitrogen bottle. PG&E replaced the nitrogen bottle in the field.



PG&E Response:

We agree with the finding of the nitrogen bottle needing to be replaced on Bank 4 Spare at Ignacio Substation. This issue was corrected onsite by our QEW on the day of the field audit.


- 4.6. Transformer Bank 4 C Phase has an empty nitrogen bottle. PG&E replaced the nitrogen bottle in the field.



PG&E Response:

We agree with the finding of the nitrogen bottle needing to be replaced on Bank 4 C Phase at Ignacio Substation. This issue was corrected onsite by our QEW on the day of the field audit.

- 4.7. Transformer Bank 4 B Phase has an empty nitrogen bottle. PG&E replaced the nitrogen bottle in the field.



PG&E Response:

We agree with the finding of the nitrogen bottle needing to be replaced on Bank 4 B Phase at Ignacio Substation. This issue was corrected onsite by our QEW on the day of the field audit.

- 4.8. Transformer Bank 5 has an empty nitrogen bottle. PG&E has existing Notification #128029498 for this issue.



PG&E Response:

The LC notification that ESRB listed is for the bird's nest at CB 102 (listed below) and not for empty nitrogen, which is LC 128031310. We agree with the finding that Transformer Bank 5 has an empty nitrogen bottle at Ignacio Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128031310. This work was completed on 02/06/2024.

- 4.9. High Voltage Circuit Breaker 322 SF6 pressure gauge is reading in the red alarm area. PG&E has recently replaced the SF6 pressure gauge, but the alarm has persisted.



PG&E Response:

We agree with the finding of the high voltage circuit breaker 322 SF6 pressure gauge needing to be replaced at Ignacio Substation. We created notification 128139455 and this work was completed on 04/16/2024.

- 4.10. Circuit Breaker 212 has a faded counter. PG&E has existing Notification #125854553 for the circuit breaker mechanical service, when the counter will be replaced.



PG&E Response:

We agree with the finding of the faded counter on circuit breaker 212 at Ignacio Substation. This work was completed during the mechanism service on PR 125854553 on 04/02/2024.

4.11. Circuit Breaker 102 has bird's nests. PG&E has existing Notification #128029498 for this issue.



PG&E Response:

We agree with the finding of a bird's nest at Circuit Breaker 102 at Ignacio Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029498. This work was completed on 03/24/2024.


- 4.12. Circuit Breaker 122 has bird's nests. PG&E has existing Notification #128029499 for this issue.



PG&E Response:

We agree with the finding of a bird's nest at Circuit Breaker 122 at Ignacio Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029499. This work was completed on 03/29/2024.

4.13. Circuit Breaker 142 has bird's nests.



PG&E Response:

We agree with the finding of a bird's nest at Circuit Breaker 142 at Ignacio Substation. We created notification 128137608 and this work was completed on 03/29/2024.

4.14. Circuit Breaker 1102 has a faded counter. PG&E has existing Notification #128030090 for this issue.



PG&E Response:

We agree with the finding of a faded counter on Circuit Breaker 1102 at Ignacio Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record

as notification 128030090. We will complete this work based on current work prioritization and material availability.

5. Stafford Substation

5.1. The station has expired eye wash. PG&E has existing Notification #128034682 for this issue.



PG&E Response:

We agree with the finding of expired eye wash at Stafford Substation, but do not agree that

the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128034682. This work was completed on 02/12/2024.

6. Petaluma A Substation

6.1. Bank 1 Spare Phase has low oil level and shows signs of oil weeping. PG&E has existing Notification #128026302 for this issue.



PG&E Response:

We agree with the finding of a low oil level on the Spare Bank 1 transformer at Petaluma A Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128026302. We will complete this work based on current work

prioritization and material availability.

7. Corona Substation

7.1. Station missing spare fuses. PG&E has existing Notification #128026568 for this issue.

PG&E Response:

We agree with the finding of missing fuses at Corona Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128026568. We will complete this work based on current work prioritization and material availability.

7.2. Circuit Breaker 152 has a bird's nest. PG&E removed the bird's nest in the field.



PG&E Response:

We agree with the finding of a bird's nest on Circuit Breaker 152 at Corona Substation. This issue was corrected onsite by our QEW on the day of the field audit.

8. Cotati Substation


8.1. Fulton-Molina-Cotati 60kV Potential Transformer A Phase pressure gauge is reading high. PG&E has existing Notification #128031121 for this issue.



PG&E Response:

We agree with the finding of high oil level on the Fulton-Molino-Cotati A phase PT at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128031121. We will complete this work based on current work prioritization and material availability.

8.2. Lakeville #2 60kV Potential Transformer A Phase insulator is dirty. PG&E has




existing Notification #128027924 for this issue.

PG&E Response:

We agree with the finding of moss contamination on the glass of A Phase PT at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027924. We will complete this work based on current work prioritization and material availability.

- 8.3. Lakeville #2 60kV Potential Transformer B Phase insulator is dirty. PG&E has existing Notification #128027925 for this issue.



PG&E Response:

We agree with the finding of moss contamination on the glass of B Phase PT at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027925. We will complete this work based on current work prioritization and material availability.

- 8.4. Lakeville #2 60kV Potential Transformer C Phase insulator is dirty. PG&E has

existing Notification #128027940 for this issue.



PG&E Response:

We agree with the finding of moss contamination on the glass of the C Phase PT at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027940. We will complete this work based on current work prioritization and material availability.


8.5. Motor Operate Air Switch 77 has a bird's nest. PG&E has existing Notification #128031122 for this issue.



PG&E Response:

We agree with the finding of a bird's nest at Motor Operating Air Switch 77 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128031122. This work was completed on 03/06/2024.


8.6. Transformer Bank 1 B Phase has rusted and corroded fan attachments on the radiator. PG&E has existing Notification #128030407 for this issue.



PG&E Response:

We agree with the finding of rust on the fans of the B Phase at Bank 1 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128030407. We will complete this work based on current work prioritization and material availability.

8.7. Transformer Bank 1 C Phase has rusted and corroded fan attachments on the radiator. PG&E has existing Notification #128030490 for this issue.



PG&E Response:

We agree with the finding of rust on the fans of the C Phase at Bank 1 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128030490. We will complete this work based on current work prioritization and material availability.

8.8. Transformer Bank 2 B Phase has low nitrogen. PG&E refilled the nitrogen in the field.



PG&E Response:

We agree with the finding of the nitrogen bottle needing to be replaced on B Phase of Bank 2 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128030640. This issue was corrected onsite by our QEW on 02/06/2024.


8.9. Circuit Breaker 1105/1 A Phase, B Phase, and C Phase have dirty insulators. PG&E has existing Notification #128027685 for this issue.



PG&E Response:

We agree with the finding of moss contamination on the glass of Air Switch 1105/1 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027685. We will complete this work based on current work prioritization and material availability.


8.10. Circuit Breaker 1105/3 A Phase, B Phase, and C Phase have dirty insulators. PG&E has existing Notification #128027755 for this issue.



PG&E Response:

We agree with the finding of moss contamination on the glass of Air Switch 1105/3 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027755. We will complete this work based on current work prioritization.


8.11. Circuit Breaker 1105/5 A Phase, B Phase, and C Phase have dirty insulators. PG&E has existing Notification #128027762 for this issue.



PG&E Response:

We agree with the finding of moss contamination on the glass of Air Switch 1105/5 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027762. We will complete this work based on current work prioritization.

8.12. Regulator 2/1 A Phase, B Phase, and C Phase have dirty insulators. PG&E has existing Notification #128027767 for this issue.



PG&E Response:

We agree with the finding of moss contamination on the glass of Reg 2/1 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027767. We will complete this work based on current work prioritization.

8.13. Regulator 2/3 A Phase, B Phase, and C Phase have dirty insulators. PG&E has existing Notification #128027768 for this issue.



PG&E Response:

We agree with the finding of moss contamination on the glass of Reg 2/3 at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027768. We will complete this work based on current work prioritization.


- 8.14. Regulator 2 Bypass A Phase, B Phase, and C Phase have dirty insulators. PG&E has existing Notification #128027822 for this issue.



PG&E Response:

We agree with the finding of moss contamination on the glass of Reg 2/Bypass at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027822. We will complete this work based on current work prioritization.

- 8.15. 12kV Bus E PT/1 A Phase, B Phase, C Phase have dirty insulators. PG&E has existing Notification #128027764 for this issue.



PG&E Response:

We agree with the finding of contamination on the glass of Bus E PT at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027764. We will complete this work based on current work prioritization.

8.16. 12kV Bus D PT/1 A Phase, B Phase, C Phase have dirty insulators.



PG&E Response:

We agree with the finding of contamination on the glass of Bus D PT at Cotati Substation. We created notification 128137609, added it to the workplan, and will be completed based on current work prioritization.

8.17. Bank 1 Station Service C Phase has dirty insulators. PG&E has existing Notification #128027825 for this issue.



PG&E Response:

We agree with the finding of contamination on the insulator of Station Bank 1, C Phase at Cotati Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128027825. We will complete this work based on current work prioritization.

9. Mirabel Substation

9.1. The station has expired eye wash. PG&E has existing Notification #128028246 for this issue.



PG&E Response:

We agree with the finding of expired eye wash at Mirabel Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128028246. This work was completed on 02/02/2024.

9.2. Transformer Bank 1 oil filtration system pressure gauge is reading low and indicating a possible oil leak. PG&E has existing Notification #128028370 for this issue.



PG&E Response:

We agree with the finding of a filtration oil leak at Bank 1 LTC at Mirabel Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128028370. We will complete this work based on current work prioritization and material availability.

10. Fitch Mountain Substation

10.1. The station has expired eye wash. PG&E has existing Notification #128029342 for this issue.



PG&E Response:

We agree with the finding of expired eye wash at Fitch Mountain Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029342. We will complete this work based on current work prioritization and material availability.

10.2. The station has trees and vegetation growing into the surrounding fence. PG&E has existing Notification #128029345 for this issue.



PG&E Response:

We agree with the finding of tree growth on the fence at Fitch Mountain Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029345. We will complete this work based on current work prioritization and material availability.

- 10.3. Transformer Bank 1 has an empty nitrogen tank. PG&E has existing Notification #128029712 for this issue.



PG&E Response:

We agree with the finding of the nitrogen bottle needing to be replaced on Bank 1 at Fitch Mountain Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029712. This work was completed on 02/26/2024.

- 10.4. Transformer Bank 1 High Side A Phase bushing is dirty. PG&E has existing Notification #128029566 for this issue.



PG&E Response:

We agree with the finding of oil corrosions on the bushings at Bank 1 at Fitch Mountain Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029566. This work was completed on 04/06/2024.

- 10.5. Transformer Bank 1 High Side B Phase bushing is dirty. PG&E has existing Notification #128029567 for this issue.



PG&E Response:

We agree with the finding that Transformer Bank 1 High Side B Phase bushing is dirty at Fitch Mountain Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029567. This work was completed on 02/26/2024.

10.6. Transformer Bank 1 Core Ground Bushing has an oil leak. PG&E has existing Notification #128029567 for this issue.



PG&E Response:

We agree with the finding of oil residue on the core ground bushing at Bank 1 at Fitch Mountain Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029567. This work was completed on 02/26/2024.

10.7. Transformer Bank 2 has an oil leak. PG&E has existing Notification #128029568 for this issue.



PG&E Response:

We agree with the finding of oil residue at Bank 2 at Fitch Mountain Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029568. We will complete this work based on current work prioritization and material availability.

- 10.8. Recloser 1111 has dirty insulators. PG&E has existing Capital Job #74056882, which will include the insulator cleaning.



PG&E Response:

We agree with the finding of recloser 1111 having dirty insulators at Fitch Mountain Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. These insulators will be cleaned when the new PTs are installed under the Capital Job #74056882.

11. Windsor Substation

- 11.1. The station has expired eye wash. PG&E has existing Notification #128029164 for this issue.



PG&E Response:

We agree with the finding of expired eye wash at Windsor Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128029164. This work was completed on 02/16/2024.

12. Silverado Substation

12.1. Station batteries have low water levels. PG&E has existing Notification #128030232 for this issue.



PG&E Response:

We agree with the finding of low water levels on the batteries at Silverado Substation, but

do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128030232. We will complete this work based on current work prioritization and material availability.

12.2. Circuit Switcher 166 has dirty insulators.



PG&E Response:

We agree with the finding of circuit switcher 166 at Silverado Substation. We created notification 128659725, added it to the workplan, and will be completed based on current work prioritization and material availability.

12.3. Circuit Switcher 156 has a broken and illegible gauge. PG&E has existing Notification #128031355 for this issue.



PG&E Response:

We agree with the finding of an illegible gas pressure gauge at Circuit Switcher 156 at Silverado Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128031355. We will complete this work based on current work prioritization and material availability.

12.4. Transformer Bank 1 has an oil leak on the sampling valve. PG&E has existing Notification #128031201 for this issue.



PG&E Response:

We agree with the finding of an oil leak at Bank 1 at Silverado Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128031201. We will complete this work based on current work prioritization and material availability.

13. Napa Substation

- 13.1. The station has abandoned extra animal abatement equipment. PG&E cleaned up the extra supplies in the field.



PG&E Response:

We agree with the finding of abandoned extra animal abatement equipment at Napa Substation. This issue was corrected onsite by PG&E personnel on the day of the field audit.

- 13.2. Transformer Bank 3 oil filtration system motor needs replacement. PG&E has existing Notification #128037248 for this issue.



PG&E Response:

We agree with the finding of filter issues at Bank 3 at Napa Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128037248. This work was completed on 04/15/2024.

- 13.3. Transformer Bank 3 has an oil leak from the oil filtration and transformer tank hoses. PG&E has existing Notification #128035737 for this issue.



PG&E Response:

We agree with the finding of an oil weep at Bank 3 at Napa Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128035737. We will complete this work based on current work prioritization and material availability.

13.4. Circuit Breaker 22 has a bird's nest. PG&E removed the bird's nest in the field.



PG&E Response:

We agree with the finding of a bird's nest on Circuit Breaker 22 at Napa Substation. This issue was corrected onsite by our QEW on the day of the field audit.

13.5. Regulator 2 has a bird's nest. PG&E removed the bird's nest in the field.



PG&E Response:

We agree with the finding of debris/animal abatement near Reg 2 at Napa Substation. This issue was corrected onsite by our QEW on the day of the field audit.

14. Basalt Substation

14.1. Motor Operated Air Switch 67 cannot be closed. PG&E has existing Notification #128073124 and Capital Job #74058260 for this issue.



PG&E Response:

We agree with the finding of Motor Operating Air Switch 67 needing to be replaced at Basalt Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128073124. We will complete this work based on current work prioritization and material availability.

14.2. Transformer Bank 1 B Phase has oil weeping and shows signs of a potential oil leak. PG&E has existing Notification #128030346 for this issue.



PG&E Response:

We agree with the finding of an oil weep at Bank 1 at Basalt Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128030346. We will complete this work based on current work prioritization and material availability.

14.3. Regulator 1 A Phase has a missing name plate. PG&E has existing Notification #128030768 for this issue.



PG&E Response:

We agree with the finding of missing name plates on Reg 1A at Basalt Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128030768. We will complete this work based on current work prioritization and material availability.

14.4. Regulator 1 B Phase has a missing name plate. PG&E has existing Notification #128030858 for this issue.



PG&E Response:

We agree with the finding of missing name plates on Reg 1B at Basalt Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128030858. We will complete this work based on current work prioritization and material availability.

14.5. Regulator 1 C Phase has a missing name plate. PG&E has existing Notification #128030980 for this issue.



PG&E Response:

We agree with the finding of missing name plates on Reg 5C at Basalt Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128030980. We will complete this work based on current work prioritization and material availability.

15. Parkway Substation

- 15.1. Transformer Bank 1 has rust on various points, including the radiator fins, pressure release device, and control device boxes. PG&E has existing Notification #128032301 for this issue.



PG&E Response:

We agree with the finding of rust on the sudden pressure relief on Bank 1 at Parkway Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128032301. We will complete this work based on current work prioritization and material availability.

15.2. Transformer Bank 1 has bees' nests. PG&E removed the bees' nests in the field.



PG&E Response:

We agree with the finding of a bee hives on Bank 1 at Parkway Substation. This issue was corrected onsite by our QEW on the day of the field audit.

- 15.3. Transformer Bank 1 has a leaking can of touchup paint in the main cabinet. PG&E cleaned up the paint in the field.



PG&E Response:

We agree with the finding of rust on the cabinet due to a paint can left there on Bank 1 at Parkway Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a notification 128035140. This issue was corrected onsite by our QEW on 02/08/2024.


16. Skaggs Island Substation

- 16.1. The station is missing spare fuses. PG&E has existing Notification #128014791 for this issue.

PG&E Response:

We agree with the finding of missing spare fuses at Skaggs Island Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128014791. We will complete this work based on current work prioritization and material availability.

- 16.2. Regulator 1 B Phase has a broken insulator. PG&E has existing Notification #128015371 for this issue.



PG&E Response:

We agree with the finding of a chipped bushing on Reg 1 B phase at Skaggs Island Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128015371. We will complete this work based on current work prioritization and material availability.

17. San Rafael Substation

17.1. The station has debris that needs cleaning, including an extra circuit breaker. PG&E has existing Notification #128035440 for this issue.




PG&E Response:

We agree with the finding of abandoned equipment at San Rafael Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128035440. We will complete this work based on current work prioritization and material

availability.

17.2. Transformer Bank 2 High Side B Phase bushing is chipped. PG&E painted the chipped bushing in the field to mitigate the issue.



PG&E Response:

We agree with the finding of a chipped bushing on the B phase at Bank 2 at San Rafael Substation. This issue was corrected onsite by our QEW on the day of the field audit.

17.3. Circuit Breaker 1102 Feeder Riser A Phase, B Phase, and C Phase have dirty insulators.



PG&E Response:

We agree with the finding of the rust on all three phases at Circuit Breaker 1102 at San Rafael Substation. We created notification 128659780, added it to the workplan, and will be completed based on current work prioritization and material availability.

17.4. Circuit Breaker 1000 and Circuit Breaker 1105 are leaking oil. PG&E has existing Notification #124471378 to replace both circuit breakers.



PG&E Response:

We agree with the finding of Circuit Breaker 1000 and Circuit Breaker 1105 needing to be replaced at San Rafael Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 124471378. We will complete this work based on current work prioritization and material availability.


- 17.5. Circuit Breaker 1104 has a faded counter. PG&E has existing Notification #128035308 for this issue.



PG&E Response:

We agree with the finding of a faded semaphore on Circuit Breaker 1104 at San Rafael Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128035308. We will complete this work based on current work prioritization and material availability.

- 17.6. Circuit Breaker 1109 has a faded semaphore. PG&E has existing Notification #128035307 for this issue.



PG&E Response:

We agree with the finding of a faded semaphore on Circuit Breaker 1109 at San Rafael Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128035307. We will complete this work based on current work prioritization and material availability.

18. Greenbrae Substation

18.1. Station batteries have corrosion. PG&E has existing Notification #128035199 for this issue.



PG&E Response:

We agree with the finding of corroded batteries at Greenbrae Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128035199. We will complete this work based on current work prioritization and material availability.


18.2. Transformer Bank 1 C Phase temperature gauge is cracked. PG&E has existing Notification #128036095 for this issue.



PG&E Response:

We agree with the finding of a cracked gauge on Bank 1, C phase at Greenbrae Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128036095. We will complete this work based on current work prioritization and material availability.


18.3. Transformer Bank 1 main cabinet has a conduit exposed to water intrusion. PG&E resealed the conduit in the field.



PG&E Response:

We agree with the finding of drainage on the conduit at Bank 1 at Greenbrae Substation. This issue was corrected onsite by our QEW on the day of the field audit.

18.4. Transformer Bank 1 has an oil leak at the upper main tank valve. PG&E has existing Notification #128036092 for this issue.



PG&E Response:

We agree with the finding of an oil weep at Bank 1 at Greenbrae Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128036092. This work was completed on 04/05/2024.


18.5. Circuit Breaker 1104 has a faded semaphore. PG&E replaced the semaphore in the field.



PG&E Response:

We agree with the finding of a faded semaphore on Circuit Breaker 1104 at Greenbrae Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128035297. This issue was corrected onsite by our QEW on the day of the field audit, 02/08/2024.

18.6. Motor Operated Air Switch 29 has a missing closed indicator light. PG&E has existing Notification #128035823 for this issue.



[PG&E Response:](#)

We agree with the finding of a light missing on Motor Operating Air Switch 29 at Greenbrae Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128035823. We will complete this work based on current work prioritization and material availability.

19. Bolinas Substation

19.1. Station has debris that needs cleaning. PG&E has existing Notification #121661630 for this issue.



PG&E Response:

We agree with the finding of debris in the yard at Bolinas Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 121661630. We will complete this work based on current work prioritization.

- 19.2. Transformer Bank 1 has an abandoned rag in the radiator fans. PG&E removed the rag in the field.



PG&E Response:

We agree with the finding of radiator debris at Bolinas Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128014371. However, this issue was corrected onsite by our QEW on the day of the field audit, 02/08/2024.

- 19.3. Transformer Bank 1 oil filtration system has saturated oil pads, indicating an oil leak. PG&E has existing Notification #128014126 for this issue.



PG&E Response:

We agree with the finding of a saturated oil pad at Bolinas Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128014126. This issue was corrected onsite by our QEW on the day of the field audit, 02/08/2024.

19.4. Circuit Breaker 12 has dirty insulators. PG&E has existing Notification #125844920 for this issue.



PG&E Response:

We agree with the finding of moss build up on the insulators at Bolinas Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 125844920. We will complete this work based on current work prioritization and material availability.

19.5. Circuit Breaker 1101/1 A Phase, B Phase, and C Phase have dirty bushings.




PG&E Response:

We agree with the finding of dirty insulators on all 3 phases of air switch 1101/1 at Bolinas

Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128014041. We will complete this work based on current work prioritization.


19.6. Circuit Breaker 1101/3 A Phase, B Phase, and C Phase have dirty bushings.



PG&E Response:

We agree with the finding of dirty insulators on all 3 phases of air switch 1101/3 at Bolinas Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128014041. We will complete this work based on current work prioritization.

19.7. Circuit Breaker 1101/5 A Phase, B Phase, and C Phase have dirty bushings.



PG&E Response:

We agree with the finding of dirty insulators on all 3 phases of air switch 1101/5 at Bolinas Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as notification 128014041. We will complete this work based on current work prioritization.